

Legend

- Sewer Gravity Main
- Stormwater Main
- Sewer Manhole
- Stormwater Manhole
- Catchbasin
- Parcel



Area head of slope with 10 feet of roadway. Recommend repair within next 12 months.

Area of well-constructed, effective, rip-rap repair.

Area of well-constructed, effective, rip-rap repair.

Source:
All base mapping data obtained from the Town of Falmouth Map developed by Wright-Pierce GIS Dept.

Falmouth, Maine
Slope Stability Issues
Bayshore/Shoreline Drive

PROJ NO: 11545A	DATE: Sept 2009	FIGURE: 2B
-----------------	-----------------	------------

October 21, 2009 10:41:57 AM W:\GIS_Development\Projects\11545_ME_Falmouth\PhaseA\Figures\Report\Figs_9-18-09\Fig2B_Slope_Stability_11x17.mxd